

>



Model Number: PHY111-006

Truck Mount Vacuum Blower Sutorbilt 4LL Dual Shaft PHY111-006 000-111-006

Manufacturer: HydraMaster

VAC BLOWER SUTORBILT 4LL TWIN SHAFT

Used on: Hydramaster CDS 4.5 & Hydrcat 4.5

Dual splash lubrication.

Dual drive Shaft

PHY111-006

000-111-006

Important Option

Oil level must be topped off on new blowers

Oil level must be changed after 50 hour break in period.

Oil level must be changed every 200 hours after break in period.

Gardner Denver 28G46 Brand Blower Oil Aeon PD-XD Full Synthetic Formula

Extra Heavy Duty for High Heat Applications 28G47-QT

Add to your shopping cart now!

PHY111-006

*Availability: This product was added to our catalog on Saturday 01 September, 2012*