

>



Model Number: 10004

PumpTec 10004 Kit B Valve and Orings 112 113v 217v 348 356 360 replaces 10010 10012 and 10016 GTIN 10679065070647

Manufacturer: Pumptec

PumpTec 10004 Kit B Valve and Orings 112v 112T 113v 217v 348 356 360 replaces 10010 10012 and 10016 GTIN 10679065070647

'Kit B' Valve & Seals- 112v, 113v, 217v, 348, 356, 360 valves

Note\* replaces Kits 10010, 10012, and 10016.

Allows for easier priming.

Compare to current or past OEM Associations

PX10004

Replaces kit 10012

B007PRJWWI

PT-10004

PU888196

GTIN 653341065346

10679065070647

679065070640

0679065070640

Factory \$40.10 / cost \$18.05

<https://www.dultmeier.com/products/0.901.1566/1249> \$32.50

<https://4jhoseandsupply.com/product/10004-pumptec-kit-b-valve-seal-repair-112t-112v-113c-217v-348u-350u-356u-m-valve-s-buna/> \$40.10

[https://www.tlevybeauty.com/index.php?main\\_page=product\\_info&products\\_id=888196](https://www.tlevybeauty.com/index.php?main_page=product_info&products_id=888196) \$19.80

[https://carpetcleanerdirect.com/pumptec\\_pump\\_repair\\_parts](https://carpetcleanerdirect.com/pumptec_pump_repair_parts) \$30.00

-->

Availability: This product was added to our catalog on Monday 13 June, 2011