

>



Model Number: 04-00047

Drieaz 04-00047 Vortex Air Mover Replacement Fan Blade 104311 for the F174

Manufacturer: Drieaz

Drieaz 104311: Vortex Air Mover Replacement Fan Blade for the F174

Shipping wt: 2#s

shipping dimensions: 14" x 14" x 4"

Compare to current or past OEM part number:

DP-0400047-EA

104311,

04-00047

DRI04-00047

0400047

225320383277

Optional:

Drieaz: 03-00021 Vortex Air Mover F174 Roll Spring Pin 03-00021

>



>

Dri-Eaz 04-00046 : Air Mover Grill 04-00046

<https://partsfloodequipment.com/fan-blade-12-dia-7-blade-part-number-04-00047/>

\$35.02 less 10% \$31.52

<https://www.grainger.ca/en/product/VORTEX-AIR-MOVER-REP-FAN-BLADE-FOR-F174/p/DRI04-00047> \$54.13

<https://www.cleanservinc.com/parts/restoration-equipment/dri-eaz-parts.html> \$28.80

-->

Availability: This product was added to our catalog on Wednesday 07 December, 2011