


>

CD8 A/B



Model Number: 7852.98

HydraMaster 601-004-701 PowerPack Assembly for CDS 4.8 Truckmount Vacuum and Pressure

Manufacturer: HydraMaster

All HYDRAMASTER ORDERS ARE FINAL, NON-CANCELLABLE, NO REFUNDS,
PRICES SUBJECT TO CHANGE BASED ON DATE SHIPPED!

HydraMaster 601-004-701 PowerPack Assembly for CDS 4.8 Truckmount Vacuum
and Pressure

Includes everything in photo

Important Option

Oil level must be topped off on new blowers

Oil level must be changed after 50 hour break in period.

Oil level must be changed every 200 hours after break in period.

Gardner Denver 28G46 Brand Blower Oil Aeon PD-XD Full Synthetic Formula

Extra Heavy Duty for High Heat Applications 28G47-QT

Add to your shopping cart now!

Availability: This product was added to our catalog on Tuesday 09 July, 2019