

>



Model Number: 5550590

Hypro 5550590, 2111-0002 and 3430-0226 Repair Kit for BPR Valve, 2 Viton High Temp Orings + Seat, PHY078-102 3300-0084

Manufacturer: Hypro Pumps

Repairs balanced pressure regulator 3300-0084

Also marketed under Hydramaster PHY078-102, 000-078-102

2x O-rings + Stainless seat

Includes Hypro 2111-0002 + 3430-0226 stainless seat 5550590.

>



>

Optional:

Purchase a new one  
Hypro Pump 3300-0084 BPR Balanced Pressure Regulator 0-2000 psi  
PHY169-101

*Availability: This product was added to our catalog on Monday 14 June, 2010*